	CENTRAL INTELLIGENCE AGENCY	REPORT		
	INFORMATION REPORT CONFIDENTIAL	CD NO.		
OUMTRY	Germany (Russian Zone)	DATE DISSE 5 JUL 51		
UBJECT	Repair of Russian Vessels at Warnerdinde	NO. OF PAGES 2	50X1-HUM	
LACE CQUIRED		NO. OF ENCLS.	30X1-110IVI	
NFO.		SUPPLEMENT TO REPORT NO.	50X1-HUM	
B. S. C., 31 AND : OF ITS CONTENTS	CONTAINS INFORMATION AFFECTION THE NATIONAL BEFOREACT STATES THINK THE GEARING OF THE SEPPORAGE ANY THE STATES SEA, AS AMERICAD, INC TRANSMISSION ON THE REVELATION THIS IS UNE REPRODUCTION OF THE PERSON TO PROPOSE THE PRO-	EVALUATED INFORMATION		
			50X1-HUM	
1.	SS YURI DOLGORUKI (formerly Hamburg)			
	a. Repair work on board this vessel has progre	ssed slowly 150 workers employed	50X1-HUM	
٠	on board.	~ ~ Actual a emhtched	50X1-HUM	
	b. The dock administration is picking a skelete board when she leaves Warmendade. Prospect skeleton erew have been told that she will a but will, in all probability, be towed away for everhauling.	ive members of this not go to Antwerp		
2.	SS RUS			
	Work continues very slowly on board this ver not yet been arected.	ssol. Its furmal has		
3∘	SS SOVIETSKAYA GAVAN			
	Because of shortages in special plates and e	electrical apparatus,		
	the reveir work is proceeding more slowly th	han was planced.		
4.0	the repair work is proceeding more slowly th	lan vas planned.		
4.	the repair work is proceeding nore slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned.	and put out to sea She has not rv-	50X1-HUM	
4. 5.	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on	end put out to sea	50X1-HUM	
	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied with trial run. According to workers who had accover, the dissatisfection was caused by the forceship has been lengthened she is not progelastet) and probably not suited for voyage the dock administration telieves that extend mistake.	and put out to sea She has not ru- Ith the results of hor companied her on this act that since her perly balanced (aus- es in the open sea.	50X1-HUM	
	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied with trial run. According to workers who had account, the dissatisfaction was caused by the forceship has been lengthened she is not progelasted) and probably not suited for voyage the dock administration believes that extend mistake.	and put out to sea She has not ru- Ith the results of hor companied her on this act that since her perly balanced (aus- es in the open sea. ding her bows was a	50X1-HUM	
5.	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied with trial run. According to workers who had accover, the dissatisfaction was caused by the forceship has been lengthened she is not progelastet) and probably not suited for voyage the dock administration telieves that extend mistake. CLASSIFICATION SECRET/CONTROL - U.S. CLASSIFICATION SECRET/CONTROL - U.S. CLASSIFICATION DISTRIBUTION	and put out to sea She has not ru- Ith the results of hor companied her on this act that since her perly balanced (aus- es in the open sea. ding her bows was a	50X1-HUM	
5.	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied witrial run. According to workers who had account, the dissatisfaction was caused by the foreship has been lengthened she is not progelasted) and probably not suited for voyage the dock administration believes that extend mistake. CLASSIFICATION SCORT CONTROL - U.S. CLASSIFICATION STORY CONTROL - U.S. CLASSIFICATION S	and put out to sea She has not ru- Ith the results of hor companied her on this act that since her perly balanced (susses in the open sea. ding her bows was a	50X1-HUM	
5.	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied witrial run. According to workers who had account, the dissatisfaction was caused by the foreship has been lengthened she is not proged asket) and probably not suited for voyage the dock administration believes that extend mistake. CLASSIFICATION SCORT CONTROL - U.S. (NAVY NARB DISTRIBUTION Beautiful Republic	and put out to sea She has not ro- Ith the results of hor companied her on this act that since her perly balanced (auster in the open sea. ding her bows was a conference of the companies of t	50X1-HUM	
5.	the repair work is proceeding more slowly the SS AUSEKLIS This vessel was completed for an unknown destination on turned. SS KARELIA The dock administration was not satisfied witrial run. According to workers who had account, the dissatisfaction was caused by the forceship has been lengthened she is not progelasted) and probably not suited for voyage the dock administration believes that extend mistake. CLASSIFICATION SCORT/CONTROL - U.S. (NAVY NARR FB) DISTRIBUTION Beck Ro	and put out to sea She has not ro- Ith the results of hor companied her on this act that since her perly balanced (auses) in the open sea. Sing her bows was a	50X1-HUM	

Declassified in Part - Sanitized Copy Approved for Release 2013/11/07 : CIA-RDP82-00457R007800290003-9

SECTO COMPROL - V.S. OFFICIALS OF LA

CERTRAT.	INTELL ICENCE	ACTONICY

50X1

2

6. SS MODIUM *

No work has as yet commenced on this sister ship of the Karelia.

7. SS YAKUTIA

A small repair gang is still on board this vessel engaged in cleaning and derusting work.

8. SS LENKORAN

This tanker is now almost complete, and her funnel is being exected.

9. SS ADMIRAL NACHIMOV

This vessel of allegedly 15,000 tons has not yet appeared, but her arrival is expected.

10. MOTOR VESSELS

These Soviet naval motor vessels KT 126, etc., are still lying on the ground alongside the main channel. They are covered with tarpaulin.

11. NEW STOCKS

After the preliminary measuring and clearing work had been made, this project appears to have come to a standatill. Construction work has not begun.

50X1-HUM

